SCORPION (RCP) RUST & CORROSION PROTECTANT

APPLICATION INSTRUCTIONS

RCP is a protective coating that guards against stains, streaks, oxidation, corrosion and pitting. RCP is UV stable and will never peel, chip, crack, flake or yellow. A single coat can last for several years, and it works on a variety of materials.



DIRECTIONS

Please read the entire label before using this product. The surface must be clean, dry and free from all contaminates. Especially waxes, grease, oil or any other residue. If any of these are present, thoroughly clean the surface with ACETONE. If you do not do this, RCP may have a streaky finish or not adhere properly.

TO CLEAN

New Metal – Thoroughly clean the surface with a mild soap to remove all contaminants. Once the surface has been properly cleaned apply RCP. Stained or Oxidized Aluminum – we recommend using aluminum cleaner first, this will leave the surface a clean uniform color. Once the surface is clean apply RCP.



EQUIPMENT

RCP can be applied with a brush or spray gun. Brush with natural bristle brush or 3/4" foam roller. Spray Gun – Airless spray system or HVLP guns, recommended 1.4 or 1.5 spray tip and 20 to 25 PSI.

APPLICATION

Mix thoroughly before use and while applying to the substrate. Brush apply an even coat on area to be protected. Re-coat after surface is dry to the touch, 5 to 10 minutes. Spray Gun – spray an even coat on area to be protected. Pass nozzles 8" to 12" from substrate with 25% overlap. Re-coat after surface is dry to touch, 5 to 10 minutes.

