


SCAN FOR MORE INFO PERIODICALLY CHECK THIS RECEIVER HITCH TO ENSURE ALL FASTENERS ARE TIGHT AND ALL STRUCTURAL COMPONENTS ARE SOUND CURT Manufacturing LLC. warrants this product to be free of defects in material and/or workmanship at the time of retail purchase by the original purchaser. If the product is found to be defective, CURT Manufacturing LLC. may repair or replace the product at their option, when the product is returned, prepaid, with proof of purchase. Alteration to, misuse of, or improper installation of this product voids the warranty. CURT Manufacturing LLC.'s libility is limited to repair or replacement of products found to be defective, and specifically excludes liability for incidental or consequential loss or damage. For more information log onto www.curtmfg.com, & for helpful towing tips log onto www.hitchinfo.com

This product complies with safety specifications and requirements for connecting devices and towing systems of the state of New York, V.E.S.C.Regulation V-5 and SAE J684.

2/25/2016

MAKE SURE YOUR HITCH MATCHES

### **INSTALLATION WALKTHROUGH:**



For more information log onto www.curtmfg.com, & for helpful towing tips log onto www.hitchinfo.com







- ¥
- Raise hitch into position aligning holes in side plates with weldnuts and secure using M10-1.25 x 30mm bolts and 3/8" conical toothed washers.

**<u>Note</u>:** For ease of installation, raise passenger side first then driver side.





## **INSTALLATION WALKTHROUGH:**

3. Torque all M10 fasteners to 48 ft-lbs.



# INSTALLATION IS NOW COMPLETE




For more information log onto www.curtmfg.com, & for helpful towing tips log onto www.hitchinfo.com

## **HYUNDAI TUCSON / KIA SPORTAGE**

### 7/12/2012

13066

EXCLUDING SX



- 1. Locate weldnuts in frame rails. (See Weldnut Cleaning Diagram)
- Raise hitch into position aligning holes in side plates with weldnuts and secure using M10-1.25 x 30mm bolts and 3/8" conical toothed washers. Note: For ease of installation, raise passenger side first then driver side.
- 3. Torque all M10 fasteners to 48 ft-lbs.



#### PERIODICALLY CHECK THIS RECEIVER HITCH TO ENSURE THAT ALL FASTENERS ARE TIGHT AND THAT ALL STRUCTURAL COMPONENTS ARE SOUND.

Scan for more information This product complies with safety specifications and requirements for connecting devices and towing systems of the state of New York, V.E.S.C.Regulation V-5 and SAE J684.